

General Environmental Incident Summary

Incident: 264 **Date/Time Notice:** 9/3/1996 **DEM Incident No:**
Responsible Party: Montana Dakota Utilities Co
Date Incident: 9/3/1996 **Time Incident:** **Duration:**
County: Burleigh **Twp:** 139 **Rng:** 80 **Sec:** 32 **Qtr:** SW SW
Lat: 46.81644 **Long:** -100.80470 **Method:** Derived from TRS
Location Description: BY FRAIN BAREKS

Submitted By: **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:
Contact Person: Inge Dressler
400 N 4th St
Bismarck, ND 58501

Distance Nearest Occupied Building:
Type of Incident: HYDROCARBON
Description of Released Contaminant: Transformer Oil
Volume Spilled: 100.00 gallons **Ag Related:** No
EPA Extremely Hazardous Substance: **Reported to NRC:** No
Cause of Incident:
REGULATOR BURNED OUT. SPILL CONTAINED AND CLEANED UP. LESS THAN 5 PCB.

Risk Evaluation:

of Fatalities: **# of Injuries:** **Affected Medium:**
Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:
Agencies Involved:

